

21st January 2014

POTENTIAL SAFETY ISSUE

To all owners of UD Trucks MK,PK,CK,CW,GK & GW Euro 5 models imported new and sold between 2011 and 2014.

UD Truck Distributors (NZ) Ltd is taking the precautionary measure of recalling certain Euro 5 vehicles due to the possible slow actuation of the park brake valve.

Cause:

A restriction in the exhaust port may possibly occur due to piston deterioration as a result of high humidity conditions.

Instructions:

Accordingly we would like to replace all control valves at an authorised UD Trucks dealer convenient to you. This work will take approximately 1 hour and the cost will be met by UD Truck Distributors.

Vehicles concerned:

All Euro 5 MK (GH7) vehicles up to and including chassis number 00750.

All Euro 5 PK (GH7) vehicles up to and including chassis number 01231.

All Euro 5 CW (GH11) vehicles up to and including chassis number 00430.

All Euro 5 GW (GH11) vehicles up to and including chassis number 00071.

CK17380 (GH11) chassis number 00005.

GK17420 (GH11) chassis number 00117.

Please have the valve/s replaced as soon as possible at an authorised UD dealers.

Yours Sincerely



John Gerbich
General Manager



Bryan Musgrave
National After Sales Manager